All models

1984 - 13374 / 1

Condition of corrosion protection

Painted outer surface

Edges and folded lips

Area exposed
to stone damage

Righthand side mirror image